








F16 1




F14.3A



F14 3B



F16.2



F19.4

5 · · ·		506	50%	510
		Intensity	Gain	RMS
xo2	$-T_0$	140	10	.05
	T_1	0	10	0
	T ₂	0	10	0
	•	•	•	. •
	• .	•	•	•
-	•	•	•	•
	T_{N}	140	10	.05
, .	504			

F16.5